

# SOLIDWORKS Keyboard Shortcuts

File	
New..	Ctrl+N
Open..	Ctrl+O
Browse Recent Documents..	R
Close..	Ctrl+W
Save..	Ctrl+S
Print..	Ctrl+P

Edit	
Undo..	Ctrl+Z
Redo..	Ctrl+Y
Repeat Last Command..	Enter
Select All..	Ctrl+A
Cut..	Ctrl+X
Copy..	Ctrl+C
Paste..	Ctrl+V
Delete..	Delete
Rebuild..	Ctrl+B
Rebuild All Configurations..	Ctrl+Shift+B
Copy Appearance..	Ctrl+Shift+C
Paste Appearance..	Ctrl+Shift+V

View	
Redraw..	Ctrl+R
Orientation..	SpaceBar
Zoom to Fit..	F
Previous View..	Ctrl+Shift+Z
Quick Snaps..	F3
FeatureManager Tree Area..	F9
Toolbars..	F10
Task Pane..	Ctrl+F1
Full Screen..	F11
Front	Ctrl+1
Back	Ctrl+2
Left	Ctrl+3
Right	Ctrl+4
Top	Ctrl+5
Bottom	Ctrl+6
Isometric	Ctrl+7
Normal To	Ctrl+8

Search	
Search SOLIDWORKS Help	H
Search Commands	W
Search Files and Models	I
Search Knowledge Base	K
Search Community Forum	O

Tools	
Magnified Selection..	G
Select over Geometry..	T
Select All..	Ctrl+A
Line..	L

Help	
Welcome to SOLIDWORKS..	Ctrl+F2
SOLIDWORKS Help..	H
Commands..	W
Files and Models..	I
Knowledge Base..	K
Community Forum..	O

Others	
Command option toggle	A
Expand/Collapse Tree	C
Collapse all Items.	Shift+C
Filter Edges	E
Find/Replace	Ctrl+F
Next Edge	N
Force Rebuild	Ctrl+Q
Force Rebuild All Configurations	Ctrl+Shift+Q
Shortcut Bar	S
Show Flat Tree View	Ctrl+T
Filter Vertices	V
Scroll to Feature Tree bottom	End
Toggle Notes Upper Case.	Shift+F3
Toggle Selection Filter Toolbar	F5
Toggle Selection Filters	F6
Spell Checker	F7
Hide/Show Display Pane.	F8
Scroll to Feature Tree top	Home
Next Command Manager Tab	Ctrl+Next
Select Annotation View	SingleQuote
Previous Command Manager Tab	Ctrl+Prior
View Selector	Ctrl+SpaceBar
Filter Faces	X
Accept Edge	Y
Zoom Out	Z
Zoom In	Shift+Z
Move Breadcrumbs / Confirmation	D
Hide Hovered-over Component	TAB
Show Hovered-over Component	Shift+TAB
Show all hidden Components	Ctrl+Shift+TAB
Select over Geometry	T